#### FILE NOTATIONS

Entered in NID File Location Map Pinned Card Indexed		Checked by Chief Approval Letter Disapproval Letter	10-18-6
COMPLETION DATA:			
Date Well Completed	11-19-68	Location Inspected	
OW WW TA.		Bond released	
GW OS PA.	••••	State or Fee Land	•••••
4.3	LOGS FII	ED	
Driller's Log. 2.3	67.		
Electric Logs (No.)			
E I	Dual I Lat	GR-N Micro	
ob bonic GR	Lat N	fi_T a	- <del>-</del>
wLog CCLog.	••••• Others	Struation De	ust.

(Da) 9-10-90

#### October 15, 1968

United States Geological Service 8416 Federal Building 125 South State Street Salt Lake City. Utah 84111

Attention: District Engineer

#### Gentlemen:

Attached herewith you will find original and two carbon copies of Application for Permit to Drill on Federal Lease #U-0142173 in Garfield County, Utah.

Assignments of 60% of the interest of A. A. Schoenfeld and Jack Q. Frizzell in favor of Cleary Funds Inc. have already been forwarded to the Bureau of Land Management covering the drill site lease.

Messrs. Schoenfeld and Frizzell have been requested to furnish you a Designation of Operator in favor of Cleary Funds Inc. covering the SE/4 of Section 20-36S-10E SEM, and we have made application for the required \$10,000 bond which should be delivered direct to your office from our surety.

if anything further is needed in connection with this matter or if you have any questions, please contact the undersigned at Area Code 405, telephone number 232-0311 collect. Your early attention to this matter will be appreciated as we would like to commence drilling operations, if possible, within the next few days.

Yours very truly,

CLEARY FUNDS INC.

Donald C. McGuffee

#### Enclosures

cc: State of Utah
Oil and Gas Conservation Commission
State Capitol Building
Salt Lake City, Utah

The API number assigned to this well is 43-017-30006 (see Bulletin D12 published by the American Petroleum Institute).

Very truly yours,

#### DIVISION OF OIL & GAS CONSERVATION

CLEON B. FEIGHT DIRECTOR

CBF:sc

cc: U. S. Geological Survey
Rodney Smith District Engineer
8416 Federal Building
Salt Lake City, Utah

#### SUBMIT IN T **ICATE**\*

(Other instructions on reverse side)


Form approved. Budget Bureau No. 42-R1425.

### UNITED STATES DEPARTMENT OF THE INTERIOR

			NTERIOR	1	5. LEASE DESIGNATION AND SERIOUS U-0142173
		OGICAL SURV			• • • • • • • • • • • • • • • • • • • •
	N FOR PERMIT	TO DRILL, I	DEEPEN, OR PLUG E	BACK	6. IF INDIAN, ALLOTTER OR TRIBE
1a. TYPE OF WORK  DI  b. TYPE OF WELL	RILL XX	DEEPEN	PLUG BA	ск 🗆 📑	7. UNIT AGREEMENT NAME NONE
OIL []	GAS WELL OTHER		SINGLE MULTIF	LE	8. FARM OR LEASE NAME Federal
Cleary Fun					9. WELL NO.
3. ADDRESS OF OPERATOR 310 Kermac	Bullding, Okla	homa City,	Oklahoma 73102		10. Field And Pool, OR WILDCA
4. LOCATION OF TELL	Beport logation elearly as	d in accordance with	th any State requirements.*) th of south line an	<u> </u>	Wildcat
	west of east li			·  -	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
At proposed prod. zo			<b>,</b>		20-T365 -R10E, SLM
4. DISTANCE IN MILES	AND DIRECTION FROM NE	AREST TOWN OR POS	T OFFICE*		12. COUNTY OR PARISH 13. STA
15. DISTANCE FROM PRO	POSED*		16. NO. OF ACRES IN LEASE	17. NO. OF	ACBES ASSIGNED
LOCATION TO NEARE PROPERTY OR LEASE	ST	660 feet	1280	TO THI	a wall 160
18. DISTANCE FROM PRO TO NEAREST WELL, OR APPLIED FOR, ON T	DRILLING, COMPLETED,	None	19. PROPOSED DEPTH	20. ROTARI	OR CABLE TOOLS
21. ELEVATIONS (Show w	whether DF, RT, GR, etc.)		·		22. APPROX. DATE WORK WILL
	O FEAGI			5.	October 20, 19
23.		PROPOSED CASI	NG AND CEMENTING PROGR.	AM.	
SIZE OF HOLE	SIZE OF CASING	WEIGHT PER F			QUANTITY OF CEMENT
15" *8=3/k ream	/3-3/\$" / 9-5/8" /	36#	150'		sacks V
*0-3/54 Team			1,000	- 200	
8-3/Li	5-1/2" V	14#	4,770	200	secks
*our prognos	is is set up to	set the 15	onductor pipe at	150' an	d air and mist dri
*our prognos 8-3/4" hole impossible to	is is set up to to total depth o mist drill, w 8" casing. Pro Navajo Wingate Chinle Shinarump Moenkopi	set the 15 of possible e plan to regnosis tops 1460 2700 2340 3600 3645		15 <b>0' en</b> e Navajo	d air and mist dri @ 1460' makes it m 8-3/4" to 12-1/4
*our prognos 8-3/4" hole impossible to	is is set up to to total depth o mist drill, w 8" casing. Pro Navajo Wingate Chinle Shinarump Moenkopi White Rim	set the 15 of possible e plan to re gnosis tops 1460 2700 2940 3600	conductor pipe at If water from the mam approximately 1	15 <b>0' en</b> e Navajo	d air and mist dri o @ 1460' makes it
*our prognos 8-3/4" hole impossible to and set 9-5/6	is is set up to to total depth o mist drill, w 8" casing. Pro Navajo Wingate Chinle Shinarump Moenkopi White Rim Cedar Mesa  BE PROPOSED PROGRAM: If o drill or deepen direction	set the 15' if possible e plan to re gnosis tops 1460 2700 2940 3600 3645 3930 4720	conductor pipe at If water from the mam approximately 1	150' en e Navajo 600' fro	d air and mist drilling 1460' makes it m 8-3/4" to 12-1/4"
*our prognos 8-3/4" hole impossible to and set 9-5/6  IN ABOVE SPACE DESCRIT zone. If proposal is to preventer program, if a	is is set up to to total depth o mist drill, w 8" casing. Pro Navajo Wingate Chinle Shinarump Moenkopi White Rim Cedar Mesa  BE PROPOSED PROGRAM: If o drill or deepen direction any	set the 15' if possible e plan to re gnosis tops 1460 2700 2940 3600 3645 3930 4720 r proposal is to deenally, give pertinen	conductor pipe at if water from the sam approximately lies are as follows:  pen or plug back, give data on pt data on subsurface locations a  Vice President Production Operation	150' en e Navajo 600' fro	d air and mist dri @ 1460' makes it m 8-3/4" to 12-1/4" ctive sone and proposed new pro and true vertical depths. Give
*our prognos 8-3/4" hole impossible to and set 9-5/6  IN ABOVE SPACE DESCRIT zone. If proposal is to preventer program, if a	is is set up to to total depth o mist drill, w 8" casing. Pro Navajo Wingate Chinle Shinarump Moenkopi White Rim Cedar Mesa  BE PROPOSED PROGRAM: If o drill or deepen direction any	set the 15' if possible e plan to re gnosis tops 1460 2700 2940 3600 3645 3930 4720 r proposal is to deenally, give pertinen	conductor pipe at If water from the sam approximately limited are as follows:	150' en e Navajo 600' fro	d air and mist drilling 1460' makes it m 8-3/4" to 12-1/4"
*our prognos 8-3/4" hole impossible to and set 9-5/6  IN ABOVE SPACE DESCRIF ZONE. If proposal is to preventer program, if a 24.  SIGNED Sammily	is is set up to to total depth o mist drill, w 8" casing. Pro Navajo Wingate Chinle Shinarump Moenkopi White Rim Cedar Mesa  BE PROPOSED PROGRAM: If o drill or deepen direction any	set the 15' if possible e plan to re gnosis tops 1460 2700 2940 3600 3645 3930 4720 r proposal is to deenally, give pertinen	conductor pipe at if water from the sam approximately lies are as follows:  pen or plug back, give data on pt data on subsurface locations a  Vice President Production Operation	150' en e Navajo 600' fro	d air and mist dri @ 1460' makes it m 8-3/4" to 12-1/4" ctive sone and proposed new pro and true vertical depths. Give
*our prognos 8-3/4" hole impossible to and set 9-5/6  IN ABOVE SPACE DESCRIF ZONE. If proposal is to preventer program, if a 24.  SIGNED Sammily	is is set up to to total depth o mist drill, w 8" casing. Pro Navajo Wingate Chinie Shinarump Moenkopi White Rim Cedar Mesa  BE PROPOSED PROGRAM: If o drill or deepen direction any	set the 15' if possible e plan to re gnosis tops 1460 2700 2940 3600 3645 3930 4720 r proposal is to deenally, give pertinen	conductor pipe at if water from the sam approximately lies are as follows:  pen or plug back, give data on pt data on subsurface locations a  Vice President Production Operation	150' en e Navajo 600' fro	d air and mist dri @ 1460' makes it m 8-3/4" to 12-1/4" ctive sone and proposed new pro and true vertical depths. Give
*Our prognos 8-3/4" hole impossible to and set 9-5/6  IN ABOVE SPACE DESCRIPTION. If proposal is to preventer program, if a 24.  SIGNED Saminul.	is is set up to to total depth o mist drill, w 8" casing. Pro Navajo Wingate Chinie Shinarump Moenkopi White Rim Cedar Mesa  BE PROPOSED PROGRAM: If o drill or deepen direction any	set the 15' if possible e plan to re gnosis tops 1460 2700 2940 3600 3645 3930 4720 r proposal is to deenally, give pertinen	pen or plug back, give data on pt data on subsurface locations a  Vice President Production Operation	150' en e Navajo 600' fro	d air and mist dri @ 1460' makes it m 8-3/4" to 12-1/4" ctive sone and proposed new pro and true vertical depths. Give

#### WELL LOCATION

660 Ft. NSL-1980 Ft. WEL SECTION 20 (Partially Surveyed) T36S RIOE SLB&M



I, William F Quinn, do hereby certify that this plat was plotted from notes of a field survey made under my direct responsibility, supervision and checking on Oct. 7-8, 1968 .

WESTERN ENGINEERS, INC. WELL LOCATION CLEARY PETROLEUM MULEY CREEK FEDERAL NO.1 GARFIELD COUNTY, UTAH

SURVEYED\_WEQ\_DRAWN\_EBE\_

GRAND JUNCTION, COLO. 10/9/68

Hen James - Chang Funda - 1-20 3550 - 3450 - acres flerening 2925 - 2875 - berg prosit string at top 7" Crelicter. T. S. of men for 90 days ACK 18/68

ato to be dispersed within 90 days - Internation t 3000/parasite some H20- Marojo

#### PLUGGING PROGRAM FORM

Name of Company Line, he Verbal Approval Given To:
Well Name: Verleyal 1-20 Sec 20 T. 36 R. 10 County: Youfild
Verbal Approval Was given to plug the above mentioned well in the following manner
TD 4010'
Ahinamip 3500'
Kiabab 3770'
White Rim 3800'
100' lement plug 3500'
50' cement sking baseaf 7' casing at 2889'
100 cement plug between 7" and 16" constructor sipe
10 sackplug at Xurface.

Date Verbally Approved: //- /8-68 Signed: Cloudla 71. Denk

January 23, 1969

Cleary Funds, Inc. 310 Kermac Building Oklahoma City, Oklahoma 73102

> Re: Well No. Cleary Funds Federal #1-20, Sec. 20, T. 36 S., R. 10 E., Garfield County, Utah.

#### Gentlemen:

1

This letter is to advise you that the "Well Completion or Recompletion Report and Log, "Subsequent Report of Abandonment and Plugging" and electric and/or radioactivity logs for the above mentioned well are due and have not been filed with this office as required by our rules and regulations.

Please complete the enclosed Forms OGC-3 and OGC-1b in duplicate and forward them to this office as soon as possible. If electric and/or radioactivity logs were not run, please make a statement to this effect in order for us to keep our records accurate and complete.

Your cooperation in this matter will be greatly appreciated.

Very truly yours,

DIVISION OF OIL & GAS CONSERVATION

SHARON C. GROVER RECORDS CLERK

8cg

Enclousre: Forms OGC-3 and OGC-1b

OGCC-1 b•		GI'DWIM IN MOIDIICAMPA	
	TATE OF UTAH	SUBMIT IN TRIPLICATE® (Other instructions on re- verse side)	5. LEASE DESIGNATION AND SERIAL NO.
DIVISION OF OIL	L AND GAS CONSERVATION	verse side)	U-0142173
			6. IF INDIAN, ALLOTTER OR TRIBE NAME
SUNDRY NO	TICES AND REPORTS O	N WELLS	
(Do not use this form for prop	cation for permit—" for such pro	ck to a different reservoir.	
	OATION TOLL I MAN PIO		7. UNIT AGREEMENT NAMB
	D & A		NONE
WELL WELL OTHER  2. NAME OF OPERATOR	U G A		8. FARM OR LEASE NAME
CLEARY FUNDS, INC		1	FEDERAL
3. ADDRESS OF OPERATOR	•		9. WELL NO.
•	na Oklahama City Okl	i	1-20
JIU RETINAC BUILDI	ng, Oklahoma City, Okla clearly and in accordance with any S	Itate requirements.	10. FIELD AND FOOL, OR WILDCAT
See also space 17 below.) At surface	ciculty and in accordance with any o		WILDCAT
	Line & 1980' W of E Li	no of Soction)	11. SEC., T., R., M., OR BLE. AND
C 3W 3E (000 N 01 3 1	Line & 1900 w of E Li	ne or section)	SURVEY OR AREA
			20-T36S-R10E SLM
4. PERMIT NO.	15. ELEVATIONS (Show whether DF,	RT, GR, etc.)	12. COUNTY OR PARISH 18. STATE
	4989 GL		Garfield Utah
16. Check A	Appropriate Box To Indicate No	ature of Notice, Report, or Ot	her Data
NOTICE OF INT	ENTION TO:	subseque.	NT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
		SHOOTING OR ACIDIZING	ABANDONMENT* X
	ABANDON*		1 1
SHOOT OR ACIDIZE	ABANDON*	(Other)	
SHOOT OR ACIDIZE REPAIR WELL (Other)	CHANGE PLANS	Completion or Recomplet	f multiple completion on Well ion Report and Log form.) ncluding estimated date of starting and depths for all markers and zones per
REPAIR WELL  (Other)  17. DESCRIBE PROPOSED OR COMPLETED O proposed work. If well is direct nent to this work.)*  1-19-68: Set 50 sack Pl 10 sack in top	OPERATIONS (Clearly state all pertinent tionally drilled, give subsurface location of 711 casing, 100 foo	(Note: Report results of Completion or Recompletion or Recompletion or Recompletion or Recompletions and measured and true vertical stack Plug from 2925-28	ion Report and Log form.)  neluding estimated dute of starting a depths for all markers and zones per
REPAIR WELL  (Other)  17. DESCRIBE PROPOSED OR COMPLETED O proposed work. If well is direct nent to this work.)*  1-19-68: Set 50 sack Pl 10 sack in top	CHANGE PLANS  DEFINITIONS (Clearly state all pertinent tionally drilled, give subsurface locations)  ug from 3550-3450, 15	(Note: Report results of Completion or Recompletion or Recompletion or Recompletion or Recompletions and measured and true vertical stack Plug from 2925-28	ion Report and Log form.)  neluding estimated date of starting a depths for all markers and zones per
REPAIR WELL  (Other)  17. DESCRIBE PROPOSED OR COMPLETED O proposed work. If well is direct nent to this work.)*  1-19-68: Set 50 sack Pl 10 sack in top	OPERATIONS (Clearly state all pertinent tionally drilled, give subsurface location of 711 casing, 100 foo	(Note: Report results of Completion or Recompletion or Recompletion or Recompletion or Recompletions and measured and true vertical stack Plug from 2925-28	ion Report and Log form.)  neluding estimated dute of starting a depths for all markers and zones per
REPAIR WELL  (Other)  17. DESCRIBE PROPOSED OR COMPLETED O proposed work. If well is direct nent to this work.)*  1-19-68: Set 50 sack Pl 10 sack in top	OPERATIONS (Clearly state all pertinent tionally drilled, give subsurface location of 711 casing, 100 foo	(Note: Report results of Completion or Recompletion or Recompletion or Recompletion or Recompletions and measured and true vertical stack Plug from 2925-28	ion Report and Log form.)  neluding estimated dute of starting a depths for all markers and zones per
SHOOT OR ACIDIZE  REPAIR WELL  (Other)  17. DESCRIBE PROPOSED OR COMPLETED 0 proposed work. If well is direct nent to this work.)  -19-68: Set 50 sack Pl 10 sack in top	OPERATIONS (Clearly state all pertinent tionally drilled, give subsurface location of 711 casing, 100 foo	(Note: Report results of Completion or Recompletion or Recompletion or Recompletion or Recompletions and measured and true vertical stack Plug from 2925-28	ion Report and Log form.)  neluding estimated date of starting a depths for all markers and zones per
SHOOT OR ACIDIZE  REPAIR WELL  (Other)  17. DESCRIBE PROPOSED OR COMPLETED 0 proposed work. If well is direct nent to this work.)  -19-68: Set 50 sack Pl 10 sack in top	OPERATIONS (Clearly state all pertinent tionally drilled, give subsurface location of 711 casing, 100 foo	(Note: Report results of Completion or Recompletion or Recompletion or Recompletion or Recompletions and measured and true vertical stack Plug from 2925-28	ion Report and Log form.)  neluding estimated date of starting a depths for all markers and zones per
REPAIR WELL  (Other)  7. DESCRIBE PROPOSED OR COMPLETED 0 proposed work. If well is direct nent to this work.)  -19-68: Set 50 sack Plus 10 sack in top	OPERATIONS (Clearly state all pertinent tionally drilled, give subsurface location of 711 casing, 100 foo	(Note: Report results of Completion or Recompletion or Recompletion or Recompletion or Recompletions and measured and true vertical stack Plug from 2925-28	ion Report and Log form.)  neluding estimated dute of starting a depths for all markers and zones per
REPAIR WELL  (Other)  7. DESCRIBE PROPOSED OR COMPLETED 0 proposed work. If well is direc nent to this work.)*  -19-68: Set 50 sack Pl 10 sack in top	OPERATIONS (Clearly state all pertinent tionally drilled, give subsurface location of 711 casing, 100 foo	(Note: Report results of Completion or Recompletion or Recompletion or Recompletion or Recompletions and measured and true vertical stack Plug from 2925-28	ion Report and Log form.)  neluding estimated dute of starting a depths for all markers and zones per
REPAIR WELL  (Other)  7. DESCRIBE PROPOSED OR COMPLETED 0 proposed work. If well is direct nent to this work.)  -19-68: Set 50 sack Plus 10 sack in top	OPERATIONS (Clearly state all pertinent ctionally drilled, give subsurface location of 711 casing, 100 foo	(Note: Report results of Completion or Recompletion or Recompletion or Recompletion or Recompletions and measured and true vertical stack Plug from 2925-28	ion Report and Log form.)  neluding estimated dute of starting a depths for all markers and zones per
REPAIR WELL  (Other)  7. DESCRIBE PROPOSED OR COMPLETED 0 proposed work. If well is direct nent to this work.)  -19-68: Set 50 sack Plus 10 sack in top	OPERATIONS (Clearly state all pertinent ctionally drilled, give subsurface location of 711 casing, 100 foo	(Note: Report results of Completion or Recompletion or Recompletion or Recompletion or Recompletions and measured and true vertical stack Plug from 2925-28	ion Report and Log form.)  neluding estimated dute of starting a depths for all markers and zones per
REPAIR WELL  (Other)  7. DESCRIBE PROPOSED OR COMPLETED 0 proposed work. If well is direct nent to this work.)*  -19-68: Set 50 sack Plus 10 sack in top	OPERATIONS (Clearly state all pertinent ctionally drilled, give subsurface location of 711 casing, 100 foo	(Note: Report results of Completion or Recompletion or Recompletion or Recompletion or Recompletions and measured and true vertical stack Plug from 2925-28	ion Report and Log form.)  neluding estimated dute of starting a depths for all markers and zones per
REPAIR WELL  (Other)  7. DESCRIBE PROPOSED OR COMPLETED 0 proposed work. If well is direct nent to this work.)  -19-68: Set 50 sack Plus 10 sack in top	OPERATIONS (Clearly state all pertinent ctionally drilled, give subsurface location of 711 casing, 100 foo	(Note: Report results of Completion or Recompletion or Recompletion or Recompletion or Recompletions and measured and true vertical stack Plug from 2925-28	ion Report and Log form.)  neluding estimated dute of starting a depths for all markers and zones per
REPAIR WELL  (Other)  7. DESCRIBE PROPOSED OR COMPLETED 0 proposed work. If well is direct nent to this work.)  -19-68: Set 50 sack Plus 10 sack in top	OPERATIONS (Clearly state all pertinent ctionally drilled, give subsurface location of 711 casing, 100 foo	(Note: Report results of Completion or Recompletion or Recompletion or Recompletion or Recompletions and measured and true vertical stack Plug from 2925-28	ion Report and Log form.)  neluding estimated dute of starting a depths for all markers and zones per
REPAIR WELL  (Other)  7. DESCRIBE PROPOSED OR COMPLETED 0 proposed work. If well is direct nent to this work.)  -19-68: Set 50 sack Plus 10 sack in top	OPERATIONS (Clearly state all pertinent ctionally drilled, give subsurface location of 711 casing, 100 foo	(Note: Report results of Completion or Recompletion or Recompletion or Recompletion or Recompletions and measured and true vertical stack Plug from 2925-28	ion Report and Log form.)  neluding estimated dute of starting a depths for all markers and zones per
SHOOT OR ACIDIZE  REPAIR WELL  (Other)  17. DESCRIBE PROPOSED OR COMPLETED 0 proposed work. If well is direct nent to this work.)  -19-68: Set 50 sack Pl 10 sack in top	OPERATIONS (Clearly state all pertinent ctionally drilled, give subsurface location of 711 casing, 100 foo	(Note: Report results of Completion or Recompletion or Recompletion or Recompletion or Recompletions and measured and true vertical stack Plug from 2925-28	ion Report and Log form.)  neluding estimated dute of starting a depths for all markers and zones per
shoot or ACIDIZE  REPAIR WELL  (Other)  17. DESCRIBE PROPOSED OR COMPLETED 0 proposed work. If well is direct nent to this work.)*  1-19-68: Set 50 sack Pl 10 sack in top	OPERATIONS (Clearly state all pertinent ctionally drilled, give subsurface location of 711 casing, 100 foo	(Note: Report results of Completion or Recompletion or Recompletion or Recompletion or Recompletions and measured and true vertical stack Plug from 2925-28	ion Report and Log form.)  neluding estimated date of starting a depths for all markers and zones per
REPAIR WELL  (Other)  17. DESCRIBE PROPOSED OR COMPLETED O proposed work. If well is direct nent to this work.)  1-19-68: Set 50 sack Pl 10 sack in top 7'' casing annu	USERATIONS (Clearly state all pertinent stionally drilled, give subsurface locations) of 711 casing, 100 foo lus at surface.	(Note: Report results of Completion or Recompletion or Recompletion or Recompletion or Recompletions and measured and true vertical stack Plug from 2925-28	ion Report and Log form.)  neluding estimated dute of starting a depths for all markers and zones per
REPAIR WELL  (Other)  17. DESCRIBE PROPOSED OR COMPLETED 0 proposed work. If well is direct nent to this work.)*  1-19-68: Set 50 sack Pl 10 sack in top	USERATIONS (Clearly state all pertinent tionally drilled, give subsurface locations) of 7" casing, 100 foo lus at surface.	(Note: Report results of Completion or Recomplet details, and give pertinent dates, it ons and measured and true vertical sack Plug from 2925-28 t plug between 13-3/89	ion Report and Log form.)  neluding estimated dute of starting a depths for all markers and zones per
REPAIR WELL  (Other)  17. DESCRIBE PROPOSED OR COMPLETED O proposed work. If well is direct nent to this work.)  1-19-68: Set 50 sack Pl 10 sack in top 7'' casing annu	USERATIONS (Clearly state all pertinent tionally drilled, give subsurface locations) of 7" casing, 100 foo lus at surface.	(Note: Report results of Completion or Recompletion or Recompletion or Recompletion or Recompletions and measured and true vertical stack Plug from 2925-28	ion Report and Log form.)  neluding estimated date of starting a depths for all markers and zones per
SHOOT OR ACIDIZE REPAIR WELL  (Other)  17. DESCRIBE PROPOSED OR COMPLETED O proposed work. If well is direct nent to this work.)  1-19-68: Set 50 sack Pl 10 sack in top 7'' casing annu  18. I hereby certify that the foregoing SIGNED  A. A	representations (Clearly state all pertinent stionally drilled, give subsurface locations) up from 3550-3450, 15 of 7" casing, 100 foo lus at surface.	(Note: Report results of Completion or Recomplet details, and give pertinent dates, it ons and measured and true vertical sack Plug from 2925-28 t plug between 13-3/89	ion Report and Log form.)  neluding estimated dute of starting a depths for all markers and zones per
SHOOT OR ACIDIZE REPAIR WELL  (Other)  17. DESCRIBE PROPOSED OR COMPLETED O proposed work. If well is direct nent to this work.)*  1-19-68: Set 50 sack Pl 10 sack in top 711 casing annu  18. I hereby certify that the foregoing the same of the sam	representations (Clearly state all pertinent stionally drilled, give subsurface locations) up from 3550-3450, 15 of 7" casing, 100 foo lus at surface.	(Note: Report results of Completion or Recomplet details, and give pertinent dates, it ons and measured and true vertical sack Plug from 2925-28 t plug between 13-3/89	ion Report and Log form.)  neluding estimated dute of starting a depths for all markers and zones per

#### SUBMIT IN DUPLICATE\*



1		v *			j.		
rm OGCC-3				SUBMI	r in Duplicate*	1	í
		STATE	OF UTAH		(See other structions	on 5 think DESIGN	ATION AND SERIAL N
	OIL & GAS	CONSERV	ATION CO	MMISSION	reverse sid	U-014217	
WELL CO	MPLETION (	OR RECO	MPLETION	REPORT A	AND LOG*		LOTTEE OR TRIBE NAM
1a. TYPE OF WEL	L: OIL WELL	GAS WELL	DRY X	Other		7. UNIT AGREEM	ENT NAME
b. TYPE OF COM						NONE	
WELL X	OVER DEEP-	D PLUG BACK	DIFF. RESVR.	Other		S. FARM OR LEAS	SE NAME
2. NAME OF OPERAT		000 4 = 1 011				FEDERAL 9. WELL NO.	
3. ADDRESS OF OPER	TROLEUM COR	PORATION		7.11		1-20	
310 Kerma	c Building.	0klahoma	City, Okl	ahoma 7310	02	10. FIELD AND P	OOL, OR WILDCAT
4. LOCATION OF WE	LL (Report location	clearly and in c	accordance with a	ny State require	ements)*	WILDCAT	
At surface C	SW/4 SE/4,	Section	20-305-10E			OR AREA	., OR BLOCK AND SURVE
At top prod. int	erval reported belov	' As Abo	ve				
At total depth	As Above					20-T36S-R	
			14. PERMIT NO	0. D	DATE ISSUED	12. COUNTY OR PARISH	13. STATE
L5_ DATE SPUDDED	16. DATE T.D. REA	CHED   17 DATE	E COMPL. (Reads	to prod.)   to	ELEVATIONS (DF, RK	Garfield	Utah Utah . ELEV. CASINGHEAD
10-26-68 stop de d ###	11-18-68	1	1-19-68	18.	5000 KB	s, KT, GK, ETC.)*	4990
20. TOTAL DEPTH, MD		BACK T.D., MD &	TVD   22, IF MU	LTIPLE COMPL., MANY*	23. INTERVAL		CABLE TOOLS
4,010			<u> </u>			0-4010	
24. PRODUCING INTER	RVAL(S), OF THIS CO	MPLETION—TOP	, BOTTOM, NAME	(MD AND TVD)*			25. WAS DIRECTIONAL SURVEY MADE
	NO		-				NO
26. TYPE ELECTRIC A			Surveyin	g Corp. Du	ual IndLL	(2894-400q) <sup>27</sup> .	
	ated Format						Ye
28.	WEIGHT, LB./FT		NG RECORD (Re	ole size		NG RECORD	1
13-3/4	WEIGHT, LB./FT	DEPTH SE		15"	100		None None
7''	20#	289	<b>I</b>	8-3/4	285		None
2-1/16 Paras	ite string v	vas run o	utside 7"	casing			None
		NAME BARGODE			1 00	WINDLY DECORD	
29.	<del></del>	NER RECORD	SACKS CEMENT*	SCREEN (MD	30.	DEPTH SET (MD)	PACKER SET (MD)
None					, , , , , , , , , , , , , , , , , , , ,		
1. PERFORATION REG	CORD (Interval, size	and number)		32.	ACID SHOT EDA	CTURE, CEMENT SQ	HEEZE ETC
	(2.00.00.00.00.00.00.00.00.00.00.00.00.00	,		DEPTH INTE		AMOUNT AND KIND OF	
				None			
NON	ΙE						
33.*			PRO	DUCTION			
DATE FIRST PRODUCT	ION PRODUCT	NON METHOD (	lowing, gas lift,	pumping—size a	nd type of pump)	WELL STATE	rus (Producing or
<del></del>							
DATE OF TEST	HOURS TESTED	CHOKE SIZE	PROD'N. FOR TEST PERIOD	01 <b>L—в́£</b> L.	GAS-MCF.	WATER—BBL.	GAS-OIL RATIO
FLOW. TUBING PRESS.	CASING PRESSURE	CALCULATED 24-HOUR RAT	OIL-BBL.	GASM	ICF. WATE	R—BBL. OIL	GRAVITY-API (CORR.)
34. DISPOSITION OF G	AS (Sold, used for fu	el, vented, etc.)				TEST WITNESSED	вт
35. LIST OF ATTACH	MENTS					_!	
36. I hereby certify	that the foregoing	and attached in	formation is com	plete and correc	ct as determined fro	m all available recor	
STONED (	at 15 Bach	silia >	mimi n	h delas	if En	70 A 1977	1-29-69

# NSTRUCTIONS

General: This form is designed for submitting a complete and correct well completion report and log on all types of lands and leases to either a Federal agency or a State laws and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office. See instructions on items 22 and 24, and 33, below regarding separate reports for separate completions.

If not filled prior to the time this summary record is submitted, copies of all currently available logs (drillers, geologists, sample and core analysis, all types electric, etc.), formation and pressure tests, and directional surveys, should be attached hereto, to the extent required by applicable Federal and/or State laws and regulations. All attachments should be listed on this form, see item 35.

Here 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State

or Federal office for specific instructions.

Hem 18: Indicate which elevation is used as reference (where not otherwise shown) for depth measurements given in other spaces on this form and in any attachments.

Hem 22 and 24: If this well is completed for separate production from more than one interval zone (multiple completion), so state in item 24 and in item 24 show the producing interval, or intervals, top(s), bottom(s) and name(s) (if any) for only the interval reported in item 33. Submit a separate report (page) on this form, adequately identified, for each additional interval to be separately produced, showing the additional data pertinent to such interval.

Hem 29: "Sacks Cement": Attached supplemental records for this well should show the details of any multiple stage cementing and the Foration of the cementing tool.

Hem 33: Submit a separate completion report on this form for each interval to be separately produced. (See instruction for items 22 and 24 above.)

37. SUMMARY OF FOROUS ZONES SHOW ALL IMPORTANT ZONES DEPTH INTERVAL TESTED, CUSE	KOUS ZONES: SRIANT ZONES OF ! L TESTED, CUSHIO!	MARY OF FURUDE MODIES: SHOW ALL IMPORTANT ZONES OF POROSITY AND CONTENTS THEREOF DEPTH INTERVAL TESTED, CUSHION USED, TIME TOOL OPEN, FLOWIN	WTS THERROF; CORED INTERVALS; AND ALL DRILL-STEM TESTS, INCLUDING OPEN, PLOWING AND SHUT-IN PRESSURES, AND RECOVERIES	38. GEOLO	GEOLOGIC MARKERS	
FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.		TOP	ē.
				NAMB	MEAS. DEPTH	TRUE VERT. DEPTH
Navaio	1340	2340	Ss. Fresh Water	Morrison	0	!
Shinarump	3495	3520		Summerville	303	f1 11
White Rim	3770	T.D.	#		430	;
			ISI 30 mins, open $1\frac{1}{2}$ hrs, FSI 30 mins,		1185	;
		,	•	es.Navajo	1343	;
			ISIP 1267 psi, FP 1003-1255 psi, FSIP Kayent	Kayenta	2337	
				Wingate	2585	i
		- 1		Chinle	2840	e 3
			#2: 3869-3927.	Shinarump	3494	!
				Moenkopi	3520	:
				Kaibab	3760	;
				70	4010	;
F				· .		
3 196	····				·	

85 PMD

#### FILE IN QUADRUPLICATE

## STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL & GAS CONSERVATION 1588 West North Temple

SALT LAKE CITY, UTAH 8411

#### REPORT OF WATER ENCOUNTERED DURING DRILLING

Well Name & Number FEDERAL	NO. 1-20	
Operator CLEARY FUNDS. INC.		mac Building ma City, Okla, Phon€ <u>E 2-031</u> 1
Contractor Carmack Drilling		
LocationSW \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	T <u>36 ##</u> R <u>10E</u> S	Garfield County, Utah
Water Sands:		
Depth	<u>Volume</u>	Quality
From To	Flow Rate or Head	Fresh or Salty
1. Navajo 1340-2340	100 Bbls/hour	Fresh
2. <u>Shinarump 3490-3520</u>	No Measurement	Fresh
3. <u>White Rim 3770-4010</u>	(See Remarks)	Fresh
4		
5.		
	(Continued on	reverse side if necessary)
Formation Tops: (See Above	e)	
Final SIP 1272 psi.		ulphu water chlorides 200 ppm.
(b) Report on this and Regulation	ng supply forms, please in form as provided for in be and Rules of Practice at lysis has been made of the	Rule C-20, General Rules nd Procedure, (See back of form

please forward a copy along with this form.